



FZ02/3W

Guiding clamp FZ02/3W for BEHAbelt Sidewalls

Precisely adapted to the division and corrugation up to a height of 20...50 mm. Special guide clamp for butt welding BEHAbelt flex sidewalls.

Note: Hot paddle welder BEHAbelt EErgo 90 required for welding the sidewalls.

Description
Guide Clamp FZ02/3W

Order No.
FBWFZ020T22

