



FZ02/3W

Guiding clamp FZ02/3W for BEHAbelt Sidewalls

Precisely adjusted to the division and undulation up to a height of 50 mm. Special guide clamp for butt welding BEHAbelt flex belt edges.

Note: EErgo 90 required for welding the belt edge.

Description
Guide Clamp FZ02/3W

Order No.
FBWFZ020T22

