



AS02

Scissors small with stop

90° cut for round belts up to
Ø 12 mm.

Description

AS02

Order No.

FBWAS02



AS03

Scissors big with stop

For 90° cut and angle cut.

Description

AS03

Order No.

FBWAS03



AS04

Scissors big with angular stop (movable)

Scissors with movable angular stop

For 45°, 60°, 75°, 90°, 105°,
120° and 135° cuts.

Description

AS04

Order No.

FBWAS04



SE02

Edge cutter with special blade

to remove the welding bead
accurately.

Description

SE02

Order No.

FBWSE02